

# MI 3000A


## Digital Weighing Indicators

### Feature

- Multi-Functional Control purpose Indicator
  - Packer, Testing, Checker, Limit weighing modes
- A/D Sampling : 200times/sec
- 6pcs Control Relay built in - 2 set points
- Rs-232C Serial Interface 2ports built in(Standard)
- Display Resolution : 1/30,000
- Part No. Memory, Max.99
- Sub-Display units - easy to check set point values
- SMPS Power Supply - AV86~265V



### Application



### Relay Mode

	OUT 1	OUT 2	OUT 3	OUT 4	OUT 5	OUT 6
Limit ("A" Dry)	SP1	SP2	Finish	Low N.G	High N.G	Zero
Packer ("B" Dry)	SP1	SP2	Finish	Low N.G	High N.G	Zero
Checker	Low	High	OK	Low N.G	High N.G	Zero
Testing	Low	High	OK	Low N.G	High N.G	Zero
Checker 2 (Range mode)	SP1	SP1<SP2	SP2<SP3	SP3<SP4	SP4<	Zero

# MI 3500A


## Digital Weighing Indicators

### Feature

- Quantity Control Application
  - Relay output, based on Quantity set point
- Multi-Functional Control purpose Indicator
  - Packer, Checker, Limit weighing modes
- A/D Sampling : 200times/sec
- 6pcs Control Relay built in - 2 set points
- Rs-232C Serial Interface 2ports built in(Standard)
- Display Resolution : 1/30,000
- Part No. Memory, Max.99
- Sub-Display units - easy to check set point values
- SMPS Power Supply - AV86~265V



### Application



### Relay Mode

	OUT 1	OUT 2	OUT 3	OUT 4	OUT 5	OUT 6
Limit ("A" Dry)	SP1	SP2	Finish	Low N.G	High N.G	Zero
Packer ("B" Dry)	SP1	SP2	Finish	Low N.G	High N.G	Zero
Checker	Low	High	OK	Low N.G	High N.G	Zero